




BEDDING-IN PROCEDURE



CAUTION



The procedure should be only carried out on sections of the road that permit these manoeuvres to be carried out in a safe manner. Excessive braking can cause the friction material to overheat too quickly, resulting in the brake pad surface to glaze over and affect the overall braking performance during this process.