


Sujet : Passage des tuyaux d'extincteur

Conformément à l'article 253 de l'annexe J, nous vous rappelons qu'il est interdit de faire passer le tuyau d'extincteur entre l'armature de sécurité et la coque.

A ce titre, il est interdit de faire passer le tuyau d'extincteur entre le renfort de fixation de berceau avant et le passage de roue de votre 208 R2.

Merci de votre attention

L'équipe des attachés techniques



Subject: Fire extinguisher pipes

In accordance with section 253 of Appendix J, we remind you that it is not allowed to route the fire extinguisher pipe between the safety cage and the bodyshell.

As such, it is not allowed to route the fire extinguisher pipe between the front subframe mounting reinforcement and the wheel arch of your 208 R2.

Thank you for your attention.

The technical support team.

Yann CHALMETON

yann.chalmeton@mpsa.com

Téléphone : +33 1 61 31 03 06

Mobile : +33 6 31 83 00 89

Cyril DUPUY

cyril.dupuy@mpsa.com

Téléphone : +33 1 30 11 26 77

Mobile : +33 6 76 86 71 50

Christophe VELY

christophe.vely@mpsa.com

Téléphone : +33 1 61 31 03 98

Mobile : +33 7 61 51 37 92