


## **Subject : Dashboard**

To ensure a correct operation of the dashboard (ref 3S1C21719B), please check the grommet is well in place at the back of the unit. In case of a bad position, wires can scratch to the edge of the housing and eventually cause a malfunction.



To lock the grommet, the 2 lugs (diametrally opposed) must be engaged inside the housing by pushing to the center of the grommet. A small noise can be heard when correctly placed (do not use tools to put it in place).



The technical support team,

Yann CHALMETON  
[yann.chalmeton@mpsa.com](mailto:yann.chalmeton@mpsa.com)  
 Téléphone : +33 1 61 31 03 06  
 Mobile : +33 6 31 83 00 89

Cyril DUPUY  
[cyril.dupuy@mpsa.com](mailto:cyril.dupuy@mpsa.com)  
 Téléphone : +33 1 30 11 26 77  
 Mobile : +33 6 76 86 71 50

Christophe VELY  
[christophe.vely@mpsa.com](mailto:christophe.vely@mpsa.com)  
 Téléphone : +33 1 61 31 03 98  
 Mobile : +33 7 61 51 37 92