


**Subject: Manual extinguisher bracket**

Following some recent notifications from the FIA about the fixation of the manual extinguisher, it is now mandatory to fit the **anti-torpedo** device to the 2 brackets (for example with **2 screws ULF M5x10** ref PS74009A01 + **self-locking nut M5** ref PS74009A01).



The technical support team,

Yann CHALMETON  
[yann.chalmeton@mpsa.com](mailto:yann.chalmeton@mpsa.com)  
Téléphone : +33 1 61 31 03 06  
Mobile : +33 6 31 83 00 89

Cyril DUPUY  
[cyril.dupuy@mpsa.com](mailto:cyril.dupuy@mpsa.com)  
Téléphone : +33 1 30 11 26 77  
Mobile : +33 6 76 86 71 50

Christophe VELY  
[christophe.vely@mpsa.com](mailto:christophe.vely@mpsa.com)  
Téléphone : +33 1 61 31 03 98  
Mobile : +33 7 61 51 37 92