

Sujet : Déverrouilleur BV (F90534161)

Afin de fiabiliser le fonctionnement du solénoïde de déverrouillage de boîte de vitesses (pour éviter le grippage/oxydation de l'axe de déverrouillage suite à l'infiltration d'eau dans l'actionneur), nous vous recommandons de mettre de la CAF sur la partie AR de l'actionneur ainsi qu'autour du faisceau rentrant dans l'actionneur.



Merci de vérifier que le faisceau du déverrouilleur est bien maintenu autour de celui-ci par un rilsan.



L'équipe du support technique,

Subject: Gearbox unlocking solenoid (F90534161)

To increase the reliability of the unlocking solenoid (to avoid axle jamming/oxidation coming from water intrusion into the actuator), we advise you to place some silicone paste at the bottom of the solenoid as well as around the loom.



Also ensure the solenoid loom is well secured by a tie rap.



The technical support team,

Damien Arbonnier
damien.arbonnier@mpsa.com
Tel : +33 1 61 31 00 24
Mobile : +33 6 74 56 77 86

Christophe Vely
christophe.vely@mpsa.com
Tel: +33 1 30 84 03 98
Mobile : +33 7 61 51 37 92