

## **Sujet: Modification du radiateur d'eau de série (1330P8)**




Suite à une non-conformité détectée lors du dernier rallye WRC d'Espagne, nous tenons à vous préciser les modifications à faire (et seulement celles indiquées) sur le radiateur de série neuf afin d'être conforme à la fiche d'homologation.

Voir schémas à la fin de ce document. Seules les parties en violet sont à modifier.

Début 2020, des radiateurs modifiés (904498828B) seront disponibles à la vente au prix de 302€ (PU HT).

### Découpe des 4 ergots



### Découpe des 3 pattes suivant cotation

L'équipe du support technique,

Damien Arbonnier  
[damien.arbonnier@mpsa.com](mailto:damien.arbonnier@mpsa.com)  
 Tel : +33 1 61 31 00 24  
 Mobile : +33 6 74 56 77 86

Christophe Vely  
[christophe.vely@mpsa.com](mailto:christophe.vely@mpsa.com)  
 Tel : +33 1 61 31 03 98  
 Mobile : +33 7 61 51 37 92


**Subject: Serial water radiator modification (1330P8)**



Following a non-compliance detected during last WRC Spain Event, we would like to remind you the modifications to do (and only those ones) to a new serial water radiator to be compliant with the homologation form.

See drawings at the end of this document. Only the purple areas must be modified.

At the beginning of 2020, new modified water radiators (904498828B) will be available at RacingShop at 302€ (UP tax excl).




The technical support team,

Damien Arbonnier  
[damien.arbonnier@mpsa.com](mailto:damien.arbonnier@mpsa.com)  
Tel : +33 1 61 31 00 24  
Mobile : +33 6 74 56 77 86



Christophe Vely  
[christophe.vely@mpsa.com](mailto:christophe.vely@mpsa.com)  
Tel: +33 1 61 31 03 98  
Mobile : +33 7 61 51 37 92

Partie Haute / Upper part:

*Cut on the same plane*  
decoupe sur le meme plan



Coupe A-A



Partie basse / Lower part :

