


Sujet : Dashboard

Afin d'assurer un fonctionnement optimal de votre dashboard (3S1C21719B), merci de contrôler que le passe-fil au dos de celui-ci est bien en place. En cas de mauvaise mise en place, des fils peuvent venir frotter sur l'arête du boîtier et finalement être endommagés conduisant à un dysfonctionnement du dashboard.



Pour verrouiller le passe-fil sur le boîtier, il faut, en poussant au centre du passe-fil, que les 2 ergots (diamétralement opposés) s'engagent bien à l'intérieur du dashboard. Un petit "clic" s'entend lors de la bonne mise place du passe-fil (ne pas utiliser de tournevis ou autre pour la mise en place).




L'équipe du support technique,

Subject: Dashboard

To ensure a correct operation of the dashboard (3S1C21719B), please check the grommet is well in place at the back of the unit. In case of a bad position, wires can scratch to the edge of the housing and eventually cause a malfunction.



To lock the grommet, the 2 lugs (diametraly opposed) must be engaged inside the housing by pushing to the center of the grommet. A small noise can be heard when correctly placed (do not use tools to put it in place).



The technical support team,

Damien Arbonnier
damien.arbonnier@mpsa.com
Tel : +33 1 61 31 00 24
Mobile : +33 6 74 56 77 86

Christophe Vely
christophe.vely@mpsa.com
Tel: +33 1 30 84 03 98
Mobile : +33 7 61 51 37 92